

Type of replacement	Cost
We Remove and they replace sand filter and Lateral	\$13,617
Pool heater replacement not installed	\$54,576
Water heater for the pool house not installed	\$7,000
Exhaust fan for Acid room not installed	\$300
Grate replacement for inside of pool	unavailable
Fixing concrete panels on deck	\$5,000
Basket filter replacement. not installed	\$6,000
Changing custom grates over the pit	\$8,400
Replace roof on the pool house and filter building	\$40,000
Fencing baby pool and slide.	\$7,500
PVC Backflow preventer for slide	\$1,742
Still leaking 4" of water every 2 days.	
Total	\$144,135